Thursday, 3/2/2006 3:07:52 PM

Kim Johnston /User:

**Process Sheet** 

Customer **Job Number**  : CU-DAR001 Dart Helicopters Services

**Drawing Name** 

: HINGE BRACKET

**Estimate Number** 

: 26035

: 10348

:NIA

: D28581

P.O. Number This issue

: 3/2/2006

S.O. No. : N/A

Part Number **Drawing Number** 

: D2858 REV B

Prsht Rev. First Issue **Previous Run** 

: NC : N/A : 24503

Туре : MACHINED PARTS Project Number **Drawing Revision**  : N/A : B

Material **Due Date**  : NIA

: 3/22/2006

Qty:

24 Um:

Each

Written By

Checked & Approved By

Removed P/O for powder coat EC Comment

**Additional Product** 

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

6061-T6 Bar 1.5" x 1.25"

Comment: Qty.:

0.1767 f(s)/Unit

Total: 4.2412 f(s)

Material: 1.50" X 1.25"

6061-T6 (QQ-A-225/8 or QQ-A-250/11 or QQ-A-200/8)

(M6061T6B15001250)

Batch M18600 - 6 Parts

06.04.01

2.0

BAND SAW

BAND SAW





Comment: BAND SAW

Cut blanks 6.02"

Note: 1 Blank Makes 3 Parts

3.0

HAAS1

HAAS CNC VERTICAL MACHINING #1





Comment: HAAS CNC VERTICAL MACHINING #1 1-Machine per folio D2858- j

4.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE

Comment: INSPECT PARTS AS THEY COME OFF MACHINE

06.04.02

Page 1

Form: rprocess

Dart Ae	rospace	e Ltd							
W/O:			WC	ORK ORDER CHANGES					
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory: N	ICR: Yes	No DQ	<b>A</b> : <u></u>	Date: _(	20/04/17
					QA: N	/C Close	d:	_ Date: _	
NCR:			WORK ORDI	ER NON-CONFORMAN	CE (NCF	<b>R</b> )			
DATE	STEP	Description of NC Section A			Verific	ation	Approval	Approval	
DATE			Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Secti			QC Inspector
					:				
							1		
,									
							······································		


NOTE: Date & initial all entries

Date: 🔻 Thursday, 3/2/2006 3:07:52 PM User: Kim Johnston **Process Sheet** Drawing Name: HINGE BRACKET Customer: CU-DAR001 Dart Helicopters Services Part Number: D28581 Job Number: 26035 Job Number: Seq. #: **Description: Machine Or Operation:** SMALL & MEDIUM FAB RESOURCE 1 SMALL FAB 1 5.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 1-Tumble 06.04.02 2-Deburr any rough edges after tumbling HAND FINISHING RESOURCE #1 HAND FINISHING1 6.0 Comment: HAND FINISHING RESOURCE #1 Acid etch and Alodine as per QSI 005 4.3 INSPECT WORK TO CURRENT STEP 7.0 QC5 24 Comment: INSPECT WORK TO CURRENT STEP 8.0 POWDER COATING POWDER COATING Comment: POWDER COATING Powder Coat Gloss White (Ref. 4.3.5.1) per Dart QSI 005 4.3 INSPECT POWDER COAT/CHEMICAL CONVERSION QC3 9.0 Comment: INSPECT POWDER COAT 10.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: DC DOCUMENT CONTROL 11.0 Comment: DOCUMENT CONTROL Inspection Level 21 a obio417 Job Completion

## **Dart Aerospace Ltd**

	p	<del></del>							
W/O:			WC	RK ORDER CHANGE	S			<del></del>	
DATE	STEP	PRO	CEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						*			
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes	No <b>DQ</b>	۸:	Date:	
					QA: N	/C Closed	l:	_ Date: _	
NCR:		V	ORK ORD	ER NON-CONFORMA	NCE (NCR	)			
DATE	STEP	Description of NC Section A	1	n B	Verific	Verification	Approval	Approval	
			Initial Chief Eng	Action Description Chief Eng	Sign & Date		Section C	Chief Eng	QC Inspector
									·

NOTE: Date & initial all entries



<u>DARY MEROS</u>	SPACE LTD	1			Work Order	26035
Obscription: }	inge brack	et			Part Number	D 2858-1
li specta n Dwg.	D2858 Rev:	В				Page 1 of 1
	FIRST	ARTICLE IN	ISPECTIO	ON CHE	CKLIST	
	X	First Artic	·	Proto		
Drawing Dimension	Tofêrance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
s.400 x -063	+.010	.400x.062				
× 171	4.002	1.173				
875	± ·010	875				
1.56	- 030	1.562			The second secon	·
342	+ -010	1.342				·
1.476		1.476				• • • • • • • • • • • • • • • • • • •
820		. 820	//	and the desired on a long a street of the		
. 328		328			Marketine and the second secon	<del>andrea de la composición de l</del>
\$.166	+.005	-168				
.354	± .010	.354				
. 965		967			Andrew Control of the	
. 147		142			**	
. 630		.631				te de la companya de
126	14	128				nemon er
.063	10	-069				manus and an incident community of the control of t
-229	1.	. 229				
-697		695	/,			
.717	The second secon	.723				Andrew Co.
1-125		5-125				
(.063	<u> </u>	i				
		6.063				to the second parameter of the second
						THE RESERVE OF THE PARTY OF THE
·					1	
<u></u>						
leasured by:	J.L /	Audited by:		Pro	ototype Appro	
Dure: O	6.04.01		6/04/02			Date:
	Change		0107100			
* 1	New Issuc					ised by Approved